Monday, 5/15/2006 1:07:01 PM Date: Linda Lacelle User: Customer Job Number **Estimate Number** P.O. Number This Issue Prsht Rev. First Issue **Previous Run** Written By Comment **Additional Product** Job Number: Seq. #: 1.0

**Process Sheet** 

**Drawing Name** 

: BASKET LID ASSEMBLY

S.O. No. : N/

**Part Number Drawing Number**  : D2989043 . D2989 REV B

Project Number

: N/A

**Drawing Revision** Material

**Due Date** 

: 5/19/2006

Qty: 1 Um:

Each

Checked & Approved By

: SPR COMMENT BELOW

: CU-DAR001 Dart Helicopters Services

Type

: 27131

: 5/15/2006

MIA

: 26721B

: Est Rev:I Removed D2989-041 05-11-03 JLM

: LARGE FAB ASSY



**Machine Or Operation:** D31821

Description:

Hinge

Comment: Qty.:

2.0000 Each(s)/Unit Total:

2.0000 Each(s)

Pick:

Qty Part number

Description Batch

D3182-1

Hinge <u>B25845</u>

B

06.02-16

2.0

Shim

Comment: Qtv.:

2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

D34423

Qty Part number

Description Batch

2 D3442-3 Shim B23545

B

06-05-16

3.0

M304EX07516F

Expanded Metal Flat Stai



8.0000 sf(s)/Unit Total:

8.0000 sf(s)

Pick:

Comment: Qty.:

15sf M304EX0.75-16F

Description Batch

Expanded Metal

MIOO JUDO

BP

06-05-1

4.0

M304TS0750W065

**Qty Part number** 

304 SQ Tube.75x.75x.065W





Comment: Qty.: 17.6400 f(s)/Unit Total: 17.6400 f(s)

3/4" x 3/4" x 0.063" wall 304/316 SStubing.

Batch: M100183

06-02-17

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	В	1	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
						1	<u> </u>	I			

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE		Description of NC		Varification	A	A					
	STEP	Section A	Initial Design Mgr	Action Description  Design Mgr	Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector			
				•							

Part No:	PAR #:	Fault Category:	NCR:	Yes No DQA:	Date: <u>06/05/17</u>
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Monday, 5/15/2006 1:07:01 PM User: Linda Lacelle **Process Sheet** Drawing Name: BASKET LID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D2989043 Job Number: 27131 Job Number: Seq. #: **Machine Or Operation:** Description: LARGE FABRICATION RESOURCE 1 5.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut (4) D2236-1 From D3166-3 As Per Dwg D2989 Note: D2989-3/-4 On -041 Bom 2-Drill holes in tubing as D2989-043 per Dwg D2989 3-Deburr and remove all markings on material 4-Weld as per Dwg D2989 and D2989-043 Assembly using Welding Table and corner Jig. Deburr as Note: Expanded metal "diamonds" must run lengthwise. Eg 2.0" along length of lid DDIMENSIONAL & WELDING INSPECTION 6.0 QC9/6 **Comment: DDIMENSIONAL & WELDING INSPECTION** 7.0 POWDER COATING **Comment: POWDER COATING** 1-Powder Coat White (Ref. 4.3.5.2) D2989-041 as per QSI 005 4.3 & Dwg D2989 a.m 06-05-191 INSPECT POWDER COAT/CHEMICAL CONVERSIO 8.0 QC3 Comment: Inspect Powder Coat DC DOCUMENT CONTROL 9.0 Comment: DOCUMENT CONTROL 06/05/19 Inspection Level 21 Job Completion W 06.05.19

## **Dart Aerospace Ltd**

W/O:			WO	<b>RK ORDER CHANGES</b>	3			· · · · · · · · · · · · · · · · · · ·	
DATE	STEP				Ву	Date	Qty	Approval Mfg / Design Mgr	Approva QC Inspecto
							<u>:</u> :		
				a					
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCF	<u></u>			
NCK:	1			Corrective Action Section B		<b>-</b> /	·	ſ	1
DATE	STEP	Description of NC Section A	Initial Design Mgr	Action Description  Design Mgr	Sign 8		ication tion C	Approval Design Mgr	Approval QC Inspecto
i									
•									
-									
		.e³ :							
Part No	):	PAR #:	Fault Category	:NCR:	Yes No	DQA:		Date:	
NOTE: Date & initial all entries			3.,		QA: N/C CI			Date:	